

19/01/2017 Hostel Visit

S.N. HALL- Sarojini Naidu Hall

- Water pipe is leaking in the washing machine room.
- The septic tanks are overflowing and needs to be in a elevated position
- Outdoor drains need to be covered. Open drains are not being cleaned and there's water logging causing bad smell across the compound of SN-MT hall area.
- Rainwater drainage pipes hanging from the roofs along the walls are all broken and needs to be repaired. This is causing water sogging in the walls.
- **Basically the hall needs thorough civil work**
- **Mess** - lots of flies are there. Flycatcher machines don't work during the day time.
- Roti dough maker and salad cutter are not cleaned properly and regularly
- Gloves and caps are not used by the kitchen staffs
- Open waste bin inside the mess which is the sole cause of attracting the flies
- Used plates collection area is extremely dirty and it is broken for which the cats are licking the used trays which is extremely unhygienic.
- So the collection area frame for keeping the used plate needs to be replaced.
- Usage of potatoes in the curry should be minimized
- **Bain Marie** in the mess is needed
- Chimney in the kitchen is needed
- Covered wastebin is needed

MT Hall- Mother Teresa Hall

- Upstairs bathroom (First floor) is leaking which is resulting in causing soaked walls
- Aquaguard is leaking which is again causing soaked walls
- The washing place in the kitchen is dirty with growing of moss in that area
- Kitchen staffs are not wearing gloves and caps
- **Bain Marie** in the mess is needed

Mrs. Barnali Chakrabarti
Mrs. Alakananda Roy
Mrs. Seema Bhattacharya
Mrs. Arundhati Patnaik

Dated: 19-1-2017

Review Done: 18-1-2017